

Applicable Models:

DHI-XVR4116HE,DHI-XVR4116HS,DHI-XVR4216A,DHI-XVR4216AN,DHI-XVR5108C,DHI-XVR5108H,DHI-XVR5108HE,DHI-XVR5108HS,DHI-XVR5208A,DHI-XVR5208AN,DHI-XVR5408L,DHI-XVR5808S,DHI-XVR7104C,DHI-XVR7104H,DHI-XVR7104HE,DHI-XVR7104HS,DHI-XVR7204A,DHI-XVR7204AN

New features:

1. Access to the OSD prompt
2. New fan and cabinet temperature data display function
3. NTP failed to reconnect
4. Optimize coaxial control protocol
5. Support more simulation front end

Optimizations & bug fixes:

1. Optimize the access ability of digital channels
2. Noise reduction of the 5X32 rating system
3. In TVI1.0, the problem is not recognized

Upgrade Guidance:

[Main Firmware]Update Main firmware to enjoy new features and multi-language. Including English, Polish, Greek, Serbian, Finnish, Romanian, Czech, Bulgarian, Hungarian, Slovenian, Danish and Swedish.