

Applicable Models:

DH-SD-29D204T-HN-PDC, DH-SD-29D204T-HN-WDC, DH-SD2904-GN-S2, DH-SD29204T-GN-W, DH-SD29204TN-GN-W, SD29204T-GN-W

New features:

NULL

Optimizations & bug fixes:

1. Repair the redundant traffic, heat map function
2. To repair the camera failed to restore the default attribute, the color turn black abnormal problem

Upgrade Guidance:

[Main Firmware]Update Main firmware to enjoy new features

[Polish Config]Please update the main firmware at first, then update this Polish Config firmware to enjoy the Polish Language