

**Applicable Models:**

XVR4104C,XVR4108C,DHI-XVR4104C,DHI-XVR4104HE,DHI-XVR4104HS,DHI-XVR4108C,DHI-XVR4108HE,DHI-XVR4108HS,DHI-XVR4204A,DHI-XVR4204AN,DHI-XVR4208A,DHI-XVR4208AN,DHI-XVR5104C,DHI-XVR5104H,DHI-XVR5104HE,DHI-XVR5104HS,DHI-XVR5204A,DHI-XVR5204AN

**New features:**

The northeast area the custom of language application and increasing forced to change the password and add the protect function, namely after the boot to choose language forced to change the password into the interface

**Optimizations & bug fixes:**

Interface language type alternatives to modify powered up for the language is to choose the mode of option to use language to describe: English, Polski, Românesc, Magyar, Suomalinen, Czechish, български, Slovensko, Ελληνικά, Српски

**Upgrade Guidance:**

[Main Firmware]Update Main firmware to enjoy new features and multi-languange.