

Applicable Models:

DHI-HCVR8204A-S3,DHI-HCVR8208A-S3,DHI-HCVR8216A-S3,DHI-HCVR8404L-S3,DHI-HCVR8408L-S3,DHI-HCVR8416L-S3,DHI-HCVR8804S-S3,DHI-HCVR8808S-S3,DHI-HCVR8808S-URH-S3,DHI-HCVR8816S-S3,DHI-HCVR8816S-URH-S3,DHI-XVR8808S,DHI-XVR8816S

New features:

1. Add the mandatory password and add the encryption protection function, that is to enter the mandatory change password interface after the boot selection language

Optimizations & bug fixes:

1. To solve the problem of "the probability of obtaining coaxial fish-eye capability probability"
2. Solve the problem of noise reduction adaptation: when day/night adaptation, it will switch to default
3. Solve the problem of AHD 720P @30fps: the new version of the cannon camera, AHD 720P @30fps is not controllable
4. The solution to the TVI camera A will not be able to switch to version B
5. Solve the problem of the night mode lock for the third party camera and return to normal during the day
6. Solve the black side problem of local small-resolution fish-eye correction box
7. Solve the problem of the audio sampling rate of IPC with 16K for 1u device and audio out of device
8. To solve the problem of "1.5u, 2U, 3U device access 32K audio sampling rate IPC HDMI sound abnormal"
9. To solve the problem of "when access to the first hard disk is abnormal, preview the time of the title jump second"
10. Solve "local change hard disk format soft restart, in the shutdown logo interface still popup system prompt" accidentally present problem
11. Solve "the temperature interface after cleaning up the configuration device, the normal temperature is high temperature"
12. Solve the problem of "400w simulated fish-eye 4K / 2K to caton"
13. Solve the problem of "insert usb flash drive, device card"

Upgrade Guidance:

[Main Firmware]Update Main firmware to enjoy new features and multi-language. Including English, Polish, Greek, Serbian, Finnish, Romanian, Czech, Bulgarian, Hungarian, Slovenian, Danish and Swedish.